



Fracture Analysis of a Clay Drainage Tile



- In agricultural drainage systems many clay tiles remain in use after up to 100 years.
- New drainage systems use corrugated PVC piping.

Clay Drainage Tile Manufacturing



- Earliest drainage tile shaped on a potter's wheel (4000 BC).
- First American mass production in 1875 (New Jersey), reaching Indiana (location of tile in this study) by 1885.



Adapted from: H.C. Plummer, *Brick and Tile Engineering Handbook of Design*, Structural Clay Products Institute, Washington, DC, 1950.

Clay Drainage Tile Manufacturing

- Shapes formed by "stiff-mud" extrusion.




Adapted from: H.C. Plummer, *Brick and Tile Engineering Handbook of Design*, Structural Clay Products Institute, Washington, DC, 1950.

Fracture Analysis Objectives



- Determine the typical cause(s) of fracture in clay drainage tiles.
- Provide an educational case study for the fracture of brittle materials.

(Given the success of corrugated PVC piping as a replacement, proposed design modifications are unnecessary.)

Fractured Clay Drainage Tile



Clay Microstructure




silicate matrix

porosity ($\approx 22\%$)
• micro vs. nano
• texture



composition:
71.5 at% Si
15.4 at% Al
6.3 at% Fe
4.3 at% K
1.6 at% Ca
0.7 at% Ti

microcracks


inclusions (crystalline)
• white - quartz (SiO_2)
• black - hematite (Fe_2O_3)
• orange - clay (silicate)




Cleavage of Quartz Inclusions



cleavage plane/surface



Fractured Clay Drainage Tile




Fracture Surface


“slow fracture” or crack propagation

- greater surface roughness
- large number of inclusions
- microcracking

pullout of inclusions



cleavage of inclusions




Fracture Toughness (K_{Ic}) Measurement

Using Vickers microhardness indentations:

$$K_{Ic} = 0.16(E/H)^{1/2}(P \cdot c_o^{-3/2})$$

G.R. Anstis *et al.*, *J. Am. Ceram. Soc.*, **64** [8] 533-538 (1981).




Using Knoop microhardness indentations:


$$E/H = \frac{0.45}{(0.14 - a/b)}$$

$$KHN = P/(0.07028 \cdot b^2)$$

D.B. Marshall, *J. Am. Ceram. Soc.*, **65** [2] C175-176 (1982).




Fracture Toughness (K_{Ic}) Measurement



$$KHN = 153 \pm 15 \text{ Kg/mm}^2$$

$$E/H = 16.7 \pm 7.3$$

$$K_{Ic} = 2.2 \pm 0.2 \text{ MPa}\cdot\text{m}^{1/2}$$



$$KHN = 158 \pm 23 \text{ Kg/mm}^2$$

$$E/H = 15.5 \pm 6.5$$

$$K_{Ic} = 2.2 \pm 0.6 \text{ MPa}\cdot\text{m}^{1/2}$$

Estimation of Failure Stress

Crack Initiation:

inclusion assumed as elliptical crack, $a = 2$ mm, $2c = 3$ mm

$$K_{Ic} = \frac{1.12 \cdot \sigma \cdot (\pi \cdot a)^{1/2}}{(3\pi/8) + (\pi/8)(a^2/c^2)} = 2.2 \pm 0.2 \text{ MPa} \cdot \text{m}^{1/2}$$

$$\sigma = 46 \pm 4 \text{ MPa}$$

Crack Propagation:

through center crack, $2a = 30$ mm, $w = 30.5$ cm

$$K_{Ic} = f(a/w) \cdot (w/\pi \cdot a)^{1/2} \cdot \sigma \cdot (\pi \cdot a)^{1/2} = 2.2 \pm 0.2 \text{ MPa} \cdot \text{m}^{1/2}$$

$$f(a/w) = [(\pi \cdot a/4w) \cdot \sec(\pi \cdot a/2w)]^{1/2} \cdot [1 - 0.025 \cdot (a/w)^2 + 0.06 \cdot (a/w)^4]$$

$$\sigma = 12 \pm 1 \text{ MPa (or less)}$$

Possible Failure Mechanisms

- 1) Crushing of tile from forces above ground.
- 2) Thermal expansion/contraction of clay.
- 3) Thermal expansion mismatch of matrix and inclusions.
- 4) Freezing of water inside tile.
- 5) Freezing of water inside clay.

Possible Failure Mechanisms

- 1) Crushing of tile from forces above ground.
- 2) Thermal expansion/contraction of clay.
- 3) Thermal expansion mismatch of matrix and inclusions.
- 4) Freezing of water inside tile.
- 5) Freezing of water inside clay.

- 1) Crushing of tile from forces above ground.
 - Tile unlikely to remain intact.
 - Mode I crack expected to initiate on inner surface.

Therefore, unlikely to be the cause of failure.

Possible Failure Mechanisms

2) Thermal expansion/contraction of clay.

- Plane theory of thermoelasticity for a thick-walled tube.
A.P. Boresi, *Elasticity in Engineering Mechanics*, Prentice-Hall, 1965.
- $E \approx 23$ GPa measured from hardness and E/H ratio.
- $E = 24.8$ GPa, $\nu = 0.05 - 0.1$
H.C. Plummer, *Brick and Tile Engineering Handbook of Design*,
Structural Clay Products Institute, Washington, DC, 1950.
- If $\Delta T \leq 10^\circ\text{C}$, $\sigma \leq 10$ MPa.

Therefore, likely to contribute to crack propagation but unlikely to be the cause of crack initiation.

Possible Failure Mechanisms

3) Thermal expansion mismatch of matrix and inclusions.

$$\alpha_{\text{quartz}} = 13.0 \cdot 10^{-6} \text{ } ^\circ\text{C}^{-1} \quad \alpha_{\text{clay}} = 5.36 \cdot 10^{-6} \text{ } ^\circ\text{C}^{-1}$$

$\Delta T \approx 1100^\circ\text{C}$ (post-firing)

Therefore, likely the cause of spalling cracks on the tile surface but unlikely to be the cause of failure.

4) Freezing of water inside tile.


- Tiles are gradually sloped to allow drainage.
- Tiles are placed below the frost line (≈ 36 in).

Therefore, unlikely to be the cause of failure.

Possible Failure Mechanisms

5) Freezing of water inside clay.



- $p(T) = -132.5 \cdot T + 1$ (atm)
- If pore considered a thick walled pressure vessel, $\sigma_{max} = p(T)$.



Possible Failure Mechanisms

5) Freezing of water inside clay.

- $K_{Ic} = (2/\pi) \cdot \sigma(T) \cdot (\pi \cdot a_c)^{1/2} \approx 2.2 \text{ MPa} \cdot \text{m}^{1/2}$



Therefore, likely to be the cause of crack initiation and contribute to crack propagation.

Summary

- 1) Freezing water inside pores or cracks in the clay was the only source able to generate the stresses necessary for crack initiation.
- 2) A crack initiated at a quartz inclusion on the outer surface of the tile. The inclusion acted as a pore that was open to water via spalling cracks due to differential thermal contraction after firing.
- 3) Crack propagation continued due to continued freezing of water in the crack and/or cyclic thermal stresses.